



What's New

 ADVANCE
DESIGN
America
2021

Improvements and corrections

New Features:

- Canadian Bridge Standard CSA-S6-19
- Canadian Steel Standard CSA-S16-19

Bug fixes:

- Flanges of a rotated I section ($\beta = 90$) was not rotating after meshing
- Bug in M_v calculation of NBC 2015
- Resetting the seismic values for NBC 2015
- Added hinges to culvert generator models
- Member orientation changing when moving the end nodes
- S6 code, M_r calculation for customized sections was not including Beta values
- Class 4 section bug for L and 2L (S16-14&19)
- Crash because of concrete shear wall without specification
- S6-06/14/19 column interaction curves problem in reinforcement window is fixed